



Generator surging wiring fix

8500-8510-8515-6150

05/08/2025

Designed with the Paving Professional in Mind.®



Machine Model: 8500-8510-8515-6150

Action Requested: Correction on auto/manual switch for screed heat

Issue Description: Leeboy has had some issues with the generator surging due to the valve driver not being powered up all the time.

Action Detail: Open screed heat box locate man/auto switch. Move yellow/red wire from post 3 to post 2 of the switch, this will give the valve driver a constant 12v preventing the generator from surging.

